



## Anton Art Center - Main Entry Sign

Location                    Mount Clemens, Michigan  
Designer / Architect     Nicolson Associates  
Duration                    Apr 2007 - Jun 2007

Scope - Soheil Mosun Limited was contracted to fabricate and install the main entry sign for the Anton Art Center in Mount Clemens, Michigan, USA.

Highlights - This project required the use of Aluminum, Bronze, Stainless Steel and Brass as well as varied finishes for each of these. The Artist's Palette Sculpture is waterjet cut 1/4" stainless steel with painted 1/4" aluminum elements, each mechanically mounted. The main structure is brushed stainless steel 1" square tubing with steel inserts in brushed brass footings. The ring and type graphics are waterjet cut 1/2" bronze with SML's special non-directional finish. The circular band and graphics are mechanically mounted to the chassis which is a brushed stainless steel square tubing structure forming a trois-foil design.



Brass and steel footings



1/2" Waterjet cut bronze graphics mechanically mounted to a tig welded ring.



Ultra fine chassis welding is seamless



The finished sign, seen here on site, uses (4) different metals and has (4) different finishes.



Painted aluminum mounted to stainless steel